
City of Baltimore Wet Smoke and Dyed	Page 1 of 2	
Sewershed: Gwynns Falls	Company: Savin	Date: 4/23/2009
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ☑ Damp ☐ Wet ☐	Supervisor: JAW
Manhole_ID: S01CC1002MH	Test ID: <u>D1032-026011</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Water Level	
0			Manhole	S01CC1002MH
18.29999924			Dye Test Visible	@ IR, 0.1gpm
20.70000076			Dye Test Visible	@ IR, 0.2gpm
26.39999962			Dye Test Visible	@ IR, 0.5 gpm
29.5			Dye Test Visible	@ IR, 0.2gpm
32.29999924			Dye Test Visible	@ IR, 1gpm
41.79999924	06		Broken	
41.79999924			Dye Test Visible	@ B, <0.1gpm
45.09999847			Abandoned Survey	DYE FLOOD COMPLETED

City of Baltimore Wet Smoke and Dyed	Page 2 of 2	
Sewershed: Gwynns Falls	Company: Savin	Date: 4/23/2009
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry Damp Wet □	Supervisor: <u>JAW</u>
Manhole_ID: S01CC1002MH	Test ID: D1032-026011	Notification Made: NA (Residents, Fire, 311)